

LUBRICATING INSTRUCTIONS FOR MULLEN® BURST TESTERS

- A. Wipe threads of the clamp lever once a week and apply a few drops of light oil.
- B. Oil motor bearings sparingly after six (6) months of service.
Apply a few drops of light oil to the oil cups every 1000 hours of service.
- C. Remove the grease once annually from the gearbox and add two (2) pounds of Shell Alvania grease.